CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL SEPTEMBER 23, 2003

10:00AM

RETURN HEARING (OLD BUSINESS)

CASE NO: CE03040379
CASE ADDR: 1919 NW 19

1919 NW 19 ST **REQUEST FOR ABATEMENT OF FINES**

OWNER: PARKWAY COMMERCE CENTER LTD

INSPECTOR: STEVE PAINE

VIOLATIONS: NFPA 1 7-3.1.1

THE FIRE SPRINKLER SYSTEM IS NOT MAINTAINED TO WORKING

ORDER.

NFPA 13 3-9.2

THE LISTED CAPS ARE MISSING ON THE FIRE DEPARTMENT SPRINKLER

CONNECTION.

NFPA 13 3-2.9.2

THE APPROVED SPRINKLER WRENCH IS MISSING FROM THE REPAIR

KIT.

NFPA 1 3-7.1

ADDRESS BAY NUMBERS ARE MISSING FROM THE DOORS.

NFPA 101 8.2.3.1.2

THERE IS NO FIRE RESISTIVE RATED WALL BETWEEN OCCUPANTS.

CASE NO: CE02110103

CASE ADDR: 1101 W COMMERCIAL BLVD **REQUEST FOR EXTENSION OF TIME**

OWNER: RUFF, FRANK TR
INSPECTOR: IVETT SPENCE-BROWN

VIOLATIONS: NFPA 101 4.5.5

THE SECOND FLOOR HAS UNENCLOSED, UNPROTECTED VERTICAL

OPENING.

CASE NO: CE02121829

CASE ADDR: 5401 E PERIMETER RD **REQUEST FOR ABATEMENT OF FINES**

OWNER: PERSONAL JET CENTER INC INSPECTOR: IVETT SPENCE-BROWN

VIOLATIONS: NFPA 101 39.2.4.2(a)

THERE IS NOT A LEGAL MEANS OF EGRESS FROM OFFICE. EXITING

IS ROUTED FROM OFFICE THROUGH THE HANGAR.

CASE NO: CE02091636
CASE ADDR: 2889 SW 16 ST
OWNER: LEWIS,D R & INEZ C

889 SW 16 ST **REQUEST FOR EXTENSION OF TIME**

INSPECTOR: WAYNE STRAWN

VIOLATIONS: FBC 104.1

THE BUILDING HAS BEEN ALTERED IN CONFIGURATION AND USE

WITHOUT OBTAINING PERMITS. THE ALTERATIONS INCLUDE, BUT MAY NOT BE LIMITED TO THE CONVERSION OF THE BUILDING TO USE AS A ROOMING HOUSE, INTERIOR PARTITIONS CONSTRUCTED, WINDOW UNIT CHANGE-OUTS, A REAR PATIO ROOF CONSTRUCTED AND STAIRWELL

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL SEPTEMBER 23, 2003 10:00AM

GUARDRAILS AND HANDRAILS INSTALLED AND SUBSEQUENTLY REPAIRED

FBC 104.2.11

AIR CONDITIONING UNITS HAVE BEEN INSTALLED MORE THAN 10 FEET ABOVE GRADE WITHOUT OBTAINING PERMITS AND SPECIFICATIONS FOR PROPER AND SAFE ATTACHMENT TO THE BUILDING.

FBC 106.1

THE BUILDING HAS BEEN CONVERTED FROM USE AS A SINGLE FAMILY BUILDING TO USE AS A ROOMING HOUSE AFTER 1955 WITHOUT OB-TAINING THE REOUIRED CERTIFICATE OF OCCUPANCY. THE BUILDING HAS NOT BEEN APPROVED FOR USE AS A ROOMING HOUSE BY BROWARD COUNTY BUILDING DEPARTMENT.

9-238

THIS SECTION IS INCLUDED FOR INFORMATIONAL PURPOSES. PLEASE TAKE SPECIAL NOTE THAT THE ORDINANCE STATES "ROOMING HOUSE SHALL CONFORM TO THE REQUIREMENTS OF THIS ARTICLE REGARDLESS --AND IRRESPECTIVE OF WHEN SUWCH STRUCTURE OR BUILDING MAY HAVE BEEN CONSTRUCTED, ALTERED OR REPAIRED".

9-277(e)

THE SECOND FLOOR BEDROOMS DO NOT HAVE THE REQUIRED SEVEN FEET IN CEILING HEIGHT. THE ROOMS VARY IN CEILING HEIGHT FROM 6' 4" TO 6' 7".

FBC 1707.4.2.1

THE WINDOWS INSTALLED ON THE SECOND FLOOR DO NOT BEAR THE REQUIRED LABELS IDENTIFYING THEM AS PASSING THE APPROVAL PROCESS WHICH WOULD DEMONSTRATE COMPLIANCE WITH REQUIRED SPECIFICATIONS.

FBC 1007.6.3

THE INTERIOR STAIRWAY PROVIDING EGRESS FROM THE SECOND FLOOR IS LESS THAN 32" WIDE. THE REQUIREMENT IS 44" ACCORDING TO THE TABLE AT 1004.

FBC 1608.2.1.2

THE HANDRAIL WHICH HAS BEEN INSTALLED DOES NOT PROVIDE THE REOUIRED STRENGTH.

FBC 1608.2.2.3

THE BALUSTRADE OF THE GUARDRAIL SYSTEM AROUND THE STAIRWELL HAS BEEN CRUDELY REPAIRED WITH SMALL ANGLE BRACKETS AND SPLICE PLATES NOT PROVIDING THE STRENGTH REQUIRED BY THE CODE.

FBC 2301.3.1

THE REAR PATIO ROOF STRUCTURE WHICH WAS BUILT WITHOUT PERMITS DOES NOT MEET THE DESIGN REQUIREMENTS OF THE CODE TO ASSURE RESISTANCE TO THE GRAVITY LOAD AND UPLIFT REQUIRE-MENTS. THE MAIN SUPPORT MEMBER AND THE RAFTERS ATTACHED SPAN A LARGE AREA WITH ONLY TWO SUPPORTING AND ANCHORING COLUMNS.

FBC 1015.1

THE ROOF OF THE REAR PATIO DOES NOT HAVE THE REQUIRED GUARDRAIL. THE REAR DOOR OF THE SECOND FLOOR OPENS DIRECTLY ONTO THE PATIO ROOF.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL SEPTEMBER 23, 2003 10:00AM

HEARING COMPUTER SCHEDULED

CASE NO: CE03022088 CASE ADDR: 3623 DAVIE BLVD

OWNER: GLASTON, H & MINERVA L

INSPECTOR: WAYNE STRAWN

VIOLATIONS: 47-25.3 A.3.d.iv.

THE REQUIRED PHYSICAL BARRIER FOR THE PURPOSE OF A BUFFER BETWEEN RESIDENTIAL AND COMMERCIAL PROPERTIES HAS NOT BEEN PROVIDED.

FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS; ROOF RAFTERS ON THE NORTHEAST CORNER OF THE ROOF AT 3623 HAVE BEEN REPAIRED, A SHORT WALL CONSTRUCTED ON THE EAST END OF THE BUILDING DESIGNED TO PREVENT ACCESS TO THE ALLEY BETWEEN BUILDINGS AND AN AWNING STRUCTURE ATTACHED TO THE REAR OF 3623.

FBC 104.2.11

VENTILATION WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO A FAN INSTALLED AT THE REAR OF 3625 (GATOR TINT) AND AN AIR CONDITIONING UNIT INSTALLED AT THE REAR OF 3623.

FBC 104.2.4

PLUMBING WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO: WASTE PIPING ON THE REAR EXTERIOR WALL OF 3635 WHICH DRAINS OUT ON THE GROUND, AND NEW SUPPLY PIPING ON THE REAR WALL OF 3625 (GATOR TINT).

FBC 104.2.5

CIRCUITS HAVE BEEN ADDED TO THE EXISTING BUILDINGS ELECTRICAL SYSTEM WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO A CIRCUIT FOR A FAN AT THE REAR OF 3635 AND A CIRCUIT FOR AN OUTSIDE LIGHT AT THE REAR OF 3635.

FBC 3401.6

THE BUILDING IS NOT BEING MAINTAINED IN A SAFE CONDITION BY REASON OF WORK DONE WITHOUT PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO: IMPROPER ROOF REPAIRS AND UNSAFE AWNING STRUCTURE (REAR) AT 3623 AND A SHORT WALL CONNECTING THIS BUILDING TO THE ADJOINING BUILDING ON THE EAST.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL SEPTEMBER 23, 2003

10:00AM

CASE NO: CE03050407 CASE ADDR: 1052 NW 53 ST

OWNER: RLM LP & RLM MANAGEMENT LLC INSPECTOR: WAYNE STRAWN

VIOLATIONS: FBC 104.2.5

CIRCUITS HAVE BEEN ADDED WITHOUT OBTAINING PERMITS. THE ALTERATIONS INCLUDE, BUT MAY NOT BE LIMITED TO, CIRCUITS FOR A WALK IN FREEZER, ADDED WALL OUTLETS AND CIRCUITS TO POWER VEHICLE-BORNE FREEZERS WHILE THEY ARE IN THE BUILDING.

FBC 104.2.11

AN AIR CONDITIONING UNIT AND A WALK-IN FREEZER HAVE BEEN IN-STALLED WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC 104.1

A ROLL UP OVERHEAD DOOR HAS BEEN INSTALLED WITHOUT OBTAINING THE REQUIRED PERMIT.

FBC,M 401.2

MOTOR VEHICLES ARE ROUTINELY BROUGHT INTO THE BUILDING AS PART OF THE BUSINESS OPERATION. THE BUILDING DOES NOT HAVE THE REQUIRED VENTILATION TO ALLOW VEHICLES INSIDE THE BUILD-ING AS SPECIFIED BY FBC,M 403.3.

FBC 3401.6

THE BUILDING IS NOT BEING MAINTAINED SAFE BY REASON OF THE ELECTRICAL WORK DONE WITHOUT PERMITS AND THE MOTOR VEHICLES INSIDE THE BUILDING WITHOUT THE PROPER VENTILATION.

CASE NO: CE03060089 CASE ADDR: 1628 SE 2 CT OWNER: KNAPP, PHILIP J INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

INSTALLED NEW WINDOWS IN THE MAIN AND REAR HOUSE WITHOUT

PERMITS.

CASE NO: CE03070264

CASE ADDR: 2025 E SUNRISE BLVD

SUNRISE MIDDLE RIVER DEV LLC& MARINA VIEW LLC OWNER:

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.9.3.1

THE PERMIT #02071202 FOR FUEL TANK REMOVAL ISSUED ON AUGUST 12, 2002, AND PERMIT # 02081866 FOR TOTAL DEMOLITION OF THE GAS STATION ISSUED IN SEPTEMBER 3, 2002, BOTH PERMITS HAVE HAD NO INSPECTIONS AND THUS ARE EXPIRED AND ARE NULL

AND VOID.

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL

SEPTEMBER 23, 2003

10:00AM

CASE NO: CE03070269 CASE ADDR: 1839 SE 1 AV

OWNER: BAUTISTA, VIDEONA B REV LIV TR

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

REMOVED ROOF SUPPORTS IN THE REAR OF THIS DUPLEX WITHOUT

A PERMIT.

FBC 104.2.4

INSTALLED NEW PLUMBING IN THE REAR OF THE DUPLEX WITHOUT A

PERMIT.

FBC 104.2.5

INSTALLED ELECTRIC WITHOUT A PERMIT.

FBC 104.2.11

INSTALLED FIVE (5) WINDOW/WALL AIR CONDITIONING UNITS

WITHOUT PERMITS.

CASE NO: CE03071725 CASE ADDR: 829 NE 1 AVE # 1

OWNER: CURATOLO, ANTONIO & CURATOLO, MARIA V

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

INSTALLED SIGNS ON BUILDING WITHOUT A PERMIT.

CASE NO: CE03071745

CASE ADDR: 401 N FT LAUD BEACH BLVD

OWNER: SABLE RESORTS INC INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

ALTERED THE STRUCTURE WITHOUT PERMITS AND NOT PER CODE

INCLUDING BUT NOT LIMITED TO :

(1) BUILT AN ACCESSIBLE RAMP

- (2) BUILT A WOODEN RAILING ON THE RAMP
- (3) INSTALLED ACCESSIBLE PARKING SPACES
- (4) INSTALLED ACCESSIBLE SIGNAGE

FBC 104.2.7

INSTALLED A SIGN FOR THE DECK RESTAURANT WITHOUT A PERMIT.

FBC 11-4.6.1

ALL COMMERCIAL BUILDINGS MUST HAVE THE PROPER NUMBER OF ACCESSIBLE PARKING SPACES PER THE CODE.

FBC 11-4.6.4

ALL BUILDINGS THAT HAVE ACCESSIBLE PARKING SPACES MUST HAVE PROPER SIGNAGE.

FBC 11-4.8

ALL BUIDINGS THAT HAVE ACCESSIBLE PARKING SPACES MUST ALSO PROVIDE ACCESSIBLE ENTRY TO THE BUILDING, INCLUDING BUT NOT LIMITED TO AN ACCESSIBLE RAMP.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL SEPTEMBER 23, 2003

10:00AM

FBC 3401.6

THE FRONT PIPE AWNING FRAME IN THE FRONT OF THE PROPERTY IS IN DISREPAIR AND RUSTING, COMPROMISING ITS INTEGRITY AND

FBC 1203.4.2

THERE ARE TWO MISSING EXHAUST FANS IN RESTROOMS OF THIS RESTAURANT.

RETURN HEARING (OLD BUSINESS)

CE03031355 CASE ADDR: 6351 NE 20 TER

REQUEST FOR EXTENSION OF TIME

GUILLEN, O M & BLANCA C OWNER:

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENT TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-MIT, THIS INCLUDES, BUT IS NOT LIMITED TO:

- 1. COLUMN POST AND ROOF ADDED ON THE REAR OF THE PROPERTY WITHOUT FIRST OBTAINING PERMITS.
- 2. INSTALLED FENCE.

FBC 3401.6

THE FOLLOWING ITEMS REQUIRE MAINTENANCE:

- 1. ROOF FASCIA ROTTED, NEED TO BE REPLACED
- 2. DOCK IN DISREPAIR, NEED TO REPAIR/REPLACE
- 3. STRUCTURAL COLUMN AND POST ARE DAMAGE/ROTTED WOOD, ON THE FRONT PORCH NEED REPAIR/REPLACE
- 4. SOFFIT ON THE WEST SIDE IS SAGGING AND BRACED WITH METAL ANGLES, NEED ENGINEER DRAWINGS AND PERMIT.

HEARING COMPUTER SCHEDULED

CASE NO: CE02110020 CASE ADDR: 915 NE 15 ST OWNER: PIERRE, MARIE L INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.2.4

PLUMBING WORK IN BATHROOM WITHOUT FIRST OBTAINING REOUIRED

PERMITS.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

SEPTEMBER 23, 2003

10:00AM

CASE NO: CE03010394

CASE ADDR: 4040 GALT OCEAN DR # 710

OWNER: ALBERO, AUGSTIN F INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENT TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMIT. THESE INCLUDE:

1. INSTALLED CORAL MARBLE SURFACE TILES ON WALLS AND BALCONY

2. REPLACE/REPAIR DRYWALL CEILING OF KITCHEN AND BATHROOM

FBC 104.2.4

INSTALLED ALL NEW PLUMBING FIXTURES IN THE BATHROOM WITHOUT FIRST OBTAINING THE REQUIRED PERMIT.

FBC 104.2.5

NEW ELECTRICAL WORK IN BATHROOM, KITCHEN AND OTHER AREAS WITHOUT FIRST OBTAINING REQUIRED PERMITS.

NOTE: PERMIT #03040720 DOES NOT COVER THE SCOPE OF THE WORK

CE03011950 CASE NO: CASE ADDR: 1827 N DIXIE HWY SALERNO, PATRICIA INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 3401.6

THE FOLLOWING ITEMS REQUIRE MAINTENANCE IN UNIT C:

- 1. ELECTRICAL WIRES HANGING IN UNIT C, NEED TO REPAIR/ REPLACE.
- 2. HOT WATER HEATER IS UNSAFE, SPARKS COMING OUT OF ELECTRICAL CONNECTIONS, OBTAIN PERMITS, REPAIR/ REPLACE AS REQUIRED.
- 3. SINK AND CABINETS IN DISREPAIR REPAIR/REPLACE AS REOUIRED.

FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-MIT. SUCH ITEMS INCLUDE, BUT ARE NOT LIMITED TO THE FOLLOW-ING:

- 1. INSTALLED NEW WINDOWS IN ALL UNITS
- 2. INSTALLED NEW DOORS

CASE NO: CE03021305

CASE ADDR: 2823 NE 26 PL
OWNER: CIRCO, CHRISTOPER W & ANGELO K

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-MIT. SUCH ITEMS INCLUDE, BUT ARE NOT LIMITED TO THE FOLLOW-ING:

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL

SEPTEMBER 23, 2003

10:00AM

- 1. DEMOLISHED INTERIOR
- 2. INSTALLED NEW INTERIOR AND EXTERIOR DOORS
- 3. INSTALLED NEW WINDOWS
- 4. STUCCO EXTERIOR WALLS5. NEW KITCHEN
- 6. NEW DRY WALL INSIDE THE HOUSE

NOTE: SOME PERMITS OBTAINED (WITHOUT ANY PLANS) AND THEY DO NOT HAVE COMPLETE SCOPE OF WORK.

FBC 104.2.4

PLUMBING WORK FOR BATHROOM AND KITCHEN WITHOUT FIRST OBTAINING REQUIRED PERMITS.

NOTE: SOME PERMITS OBTAINED (WITHOUT ANY PLANS) AND THEY DO NOT HAVE COMPLETE SCOPE OF WORK.

FBC 104.2.5

ELECTRICAL WORK IN CARPORT, WITHOUT FIRST OBTAINING REQUIRED PERMITS.

NOTE: SOME PERMITS OBTAINED (WITHOUT ANY PLANS) AND THEY DO NOT HAVE COMPLETE SCOPE OF WORK.

FBC 104.2.11

INSTALLED NEW AIR CONDITIONING UNIT AND DUCT WORK WITHOUT FIRST OBTAINING REQUIRED MECHANICAL PERMIT.

NOTE: SOME PERMITS OBTAINED (WITHOUT ANY PLANS) AND THEY

DO NOT HAVE COMPLETE SCOPE OF WORK.

CASE NO: CE03042289 CASE ADDR: 1221 NE 3 AVE

TITANS OF FORT LAUDERDALE OWNER:

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMIT. THIS INCLUDES, BUT IS NOT LIMITED TO:

- 1. NEW EXTERIOR DOORS
- 2. NEW WINDOWS
- 3. NEW KITCHEN CABINETS
- 4. NEW FENCE
- 5. NEW SIDING

FBC 104.2.4

NEW PLUMBING WORK WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- 1. PLUMBING IN KITCHEN
- 2. NEW EXTERIOR COPPER PIPING WITH VALVES

FBC 104.2.5

NEW ELECTRICAL WORK, WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

1. NEW LIGHT FIXTURES

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL SEPTEMBER 23, 2003 10:00AM

CASE NO: CE03061827

3461 GALT OCEAN DR MAGNUS, LEE CASE ADDR:

OWNER: INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-

MIT. THIS INCLUDES, BUT IS NOT LIMITED TO:

1. INSTALLED NEW EXTERIOR DOOR

FBC 3401.6

THE FOLLOWING ITEMS REQUIRE MAINTENANCE.

1. BATHROOM WINDOW, GLASS BROKEN

47-22.3 X.

WINDOW SIGNS EXCEED TWENTY PERCENT (20%) OF GLASS SURFACE.

CASE NO: CE03061868

CASE ADDR: 3200 N OCEAN BLVD # 1607

OWNER: BROWN, GARY D INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-MIT. THIS INCLUDES, BUT IS NOT LIMITED TO:

1. INSTALLED NEW DRYWALL CEILINGS

2. INSTALLED NEW DOOR

FBC 104.2.5

NEW ELECTRICAL WORK, WITHOUT FIRST OBTAINING REQUIRED

PERMITS.

CASE NO: CE02061228 CASE ADDR: 1225 NW 14 CT

OWNER: UNITED INVESTMENT FUNDING INC

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF FENCE

CODE ENFORCEMENT BOARD
CITY COMMISSION MEETING ROOM - CITY HALL
SEPTEMBER 23, 2003

SEPTEMBER 23, 200 10:00AM

CASE NO: CE02111210
CASE ADDR: 725 NW 14 TER
OWNER: AYALA,SANDRA
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 3401.6

FAILURE TO MAINTAIN THE PROPERTY. WOOD SOFFITS, FASCIA BOARDS, ROOF STRUCTURE, EXTERIOR DOORS AND ELECTRICAL

ELEMENTS REQUIRE REPAIR OR REPLACEMENT.

CASE NO: CE03021141
CASE ADDR: 1408 NW 12 ST
OWNER: RAYMOND, CHRISTOPHER
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF REPLACEMENT WINDOWS

CASE NO: CE03021244 CASE ADDR: 1316 NW 12 ST

OWNER: MCCLAM, BRAXTON & McCLAM, KIMBERLY

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE

REQUIRED BUILDING PERMITS. THIS INCLUDES BUT IS NOT

LIMITED TO:

A. INSTALLATION OF REPLACEMENT WINDOWS.

CASE NO: CE03021874
CASE ADDR: 1716 NW 8 PL
OWNER: BLAKE, MOSES
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: 47-20.13 A.

PARKING AREA IS NOT BEING MAINTAINED.

47-21.8

GROUND COVER IS NOT BEING MAINTAINED AND HAS PATCHES OF BARE SAND.

6-34

THERE ARE MORE THAN THREE (3) DOGS BEING KEPT AT THIS LOCATION, WHICH CONSTITUTES A KENNEL.

9-278 (g)

THERE ARE MISSING AND TORN SCREENS IN THE WINDOWS OF THIS LOCATION

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL SEPTEMBER 23, 2003

10:00AM

9-280(b)

THERE ARE DOORS AND WINDOWS WHICH ARE NOT WEATHER AND WATER TIGHT AND RODENT PROOF.

9-280(h)(1)

FENCE AT THIS LOCATION IS NOT BEING MAINTAINED AND HAS BROKEN, BENT OR MISSING SECTIONS.

9-306

WALLS ARE DIRTY AND PAINT IS CHIPPING AND PEELING ON BUILDING.

FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF CONCRETE PARKING AREAS
- INSTALLATION OF REPLACEMENT DOORS
- INSTALLATION OF CHAIN LINK FENCING
- D. INSTALLATION OF CONCRETE BLOCK WALLS

FBC 3401.6

FAILURE TO MAINTAIN PROPERTY. DETERIORATION OF EXTERIOR WOOD STRUCTURES INCLUDING SOFFITS, FASCIA AND ROOF.

CASE NO: CE03030070 CASE ADDR: 2158 NW 6 CT

NEW LIFE CHRISTIAN FELLOWSHIP OWNER:

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIM-ITED TO:

A. INSTALLATION OF CHAIN LINK FENCING B. INSTALLATION OF CANVAS CANOPIES.

CE03060963 CASE NO: CASE ADDR: 1417 NW 13 PL OWNER: SPATE, GERALD INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

CITY OF FORT LAUDERDALE

AGENDA

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL

SEPTEMBER 23, 2003

10:00AM

- A. INSTALLATION OF REPLACEMENT WINDOWS
- B. MODIFICATION OF FRONT PORCH COLUMNS
- C. INSTALLATION OF WALL SHEATHING AND WINDOW ENCLOSURES
- D. EXTENSION OF FRONT ROOF
 E. ENCLOSURE OF CARPORT

CASE NO: CE03062027

CASE ADDR: 4700 W PROSPECT RD OWNER: OAK TREE PLAZA ASSN INC

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. CONVERSION OF TENANT SPACE

B. INTERIOR REMODEL

CE03062535 CASE NO: CASE ADDR: 616 NW 4 AVE RHODEN, LEROY A OWNER: INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

- A. INSTALLATION OF REPLACEMENT DOORS.
- INSTALLATION OF REPLACEMENT WINDOWS.
- C. INSTALLATION OF KITCHEN CABINETS.
- D. RE-STRIPING OF PARKING AREA.

CASE NO: CE03070690 CASE ADDR: 1328 NW 19 AV SAUNDERS, DAMON INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. CONSTRUCTION OF AN ADDITION.
- B. CONVERSION OF THE ORIGINAL STRUCTURE.

FBC 104.2.4

THERE HAS BEEN MODIFICATIONS TO THE INTERIOR PLUMBING SUPPLY, VENT AND DRAIN LINE CONNECTIONS WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

REQUEST FOR ABATEMENT OF FINES

AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL SEPTEMBER 23, 2003

10:00AM

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS FOR THE ROOM ADDITIONS.

FBC 104.2.11

INSTALLATION OF AIR CONDITIONING UNITS WERE INSTALLED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 3401.6

THE PROPERTY/STRUCTURE HAS NOT BEEN MAINTAINED. THIS INCLUDES BUT IS NOT LIMITED TO:

- A. WOOD FASCIA AND ROOF IN DISREPAIR.
- B. DOORS NOT SOUND AND NEED REPLACING.
- C. WINDOWS NOT WEATHERPROOF.
- D. WINDOW SCREENS MISSING.
- E. SEWER/SEPTIC SYSTEM CONNECTIONS NOT BEING MAINTAINED.
- F. GROUND COVER/LANDSCAPE MISSING.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE02100344

CASE ADDR: 1430 SW 34 TER STEWART, NORMAN INSPECTOR: KENNETH REARDON

VIOLATIONS: 9-280(g)

THE EXTERIOR ELECTRICAL IS NOT MAINTAINED AND THERE IS LOOSE AND EXPOSED WIRED AND FIXTURES.

9-281(b)

THE YARD IS NOT BEING MAINTAINED. THE GRASS IS OVERGROWN IN AREAS AND MISSING IN OTHER AREAS. THERE IS TRASH, RUBBISH AND DEBRIS THROUGHOUT THE YARD, INCLUDING, BUT NOT LIMITED TO THE FOLLOWING:

- 1-AN OLD AIR CONDITIONING UNIT
- 2-AN OLD GAS FURNACE
- 3-OLD PVC PIPING
- 4-ABANDONED FENCING
- 5-OLD AIR CONDITIONING FREON GAS LINES
- 6-BROKEN UP CONCRETE
- 7-AN OLD TOILET
- 8-FRONT YARD SAND PILE

FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT

- 1- THE BUILDING HAS BEEN REROOFED.
- 2- INTERIOR DRYWALL WORK
- 3- KITCHEN AND BATHROOM CABINETS HAVE BEEN REMOVED
- 4- WINDOW REPLACEMENT
- 5- EXTERIOR STUCCO WORK

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL SEPTEMBER 23, 2003 10:00AM

FBC 104.2.4

THE DEMOLITION OF THE KITCHEN, BATHROOM AND WATER HEATER PLUMBING WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

FBC 104.2.5

THE INTERIOR ELECTRIC FIXTURES HAVE BEEN REMOVED AND CIRCUITS ADDED TO THE REAR AND SOUTH EXTERIOR WALLS WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

FBC 3401.6

THERE ARE LARGE STRUCTURAL CRACKS ON T5HE NORTH AND EAST EXTERIOR WALLS.

CE02110605 CASE NO: CASE ADDR: 812 SW 11 AVE OWNER: HUGUES, FRED G

INSPECTOR: KENNETH REARDON

REQUEST FOR EXTENSION OF TIME

VIOLATIONS: FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT:

- A. THE SOUTHEAST PORCH HAS BEEN ENCLOSED
- B. A SLIDING GLASS DOOR HAS BEEN ADDED TO THE SOUTH WALL
- C. THE NORTH WALL EAST WINDOW HAS BEEN REPLACED AND THE OPENING WAS ALTERED
- D. THE KITCHEN HAS BEEN REMODELED
- E. A LARGE WOOD SHED/GARAGE HAS BEEN ADDED

FBC 104.2.4

THE KITCHEN SINK HAS BEEN REPLACED WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

FBC 104.2.5

A NEW OUTLET HAS BEEN ADDED TO THE SOUTH EXTERIOR WALL, A NEW CENTRAL AIR CONDITIONING SYSTEM WIRED AND THE KITCHEN REMODELED WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

FBC 104.2.11

A CENTRAL AIR CONDITIONING SYSTEM WAS INSTALLED IN 1993 WITHOUT FIRST OBTAINING A MECHANICAL PERMIT.

FBC 104.9.3.1

THE FOLLOWING PERMITS HAVE EXPIRED SINCE NO PASSING IN-SPECTIONS WERE OBTAINED IN OVER 90 DAYS:

- A. 02080513 FOR WOOD FENCE
- B. 10162257 FOR WATER SERVICE
- C. 99062254 FOR THE POOL DECK
- D. 99040484 FOR NEW POOL
- E. 99040486 FOR POOL ELECTRIC

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL

SEPTEMBER 23, 2003

10:00AM

HEARING COMPUTER SCHEDULED

CASE NO: CE02061782 CASE ADDR: 2879 SW 14 ST

RIVERA, ORESTES P & MARTA V

OWNER: RIVERA, ORESTES INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT:

A. REPLACED THE WINDOWS.

B. REPLACED THE EXTERIOR DOORS.

C. BUILT AN ADDITION ALONG THE WEST SIDE OF THE HOUSE.

D. INSTALLED A WOOD FENCE.

FBC 106.1

OCCUPIED THE WEST SIDE ADDITION WITHOUT FIRST OBTAINING A CERTIFICATE OF OCCUPANCY FROM THE BUILDING OFFICIAL.

CASE NO: CE02121206 CASE ADDR: 624 NE 4 AV
OWNER: SWISS VILLAGE HOLDINGS INC

INSPECTOR: KENNETH REARDON

VIOLATIONS: 47-19.5 D.4.

THE FINISHED SIDE OF THE FENCE IS NOT FACING THE NEIGHBORING PROPERTY ALONG THE REAR AND SOUTH SIDE. THE FENCING MUST BE FINISHED ON BOTH SIDES WHERE VISIBLE FROM THE RIGHT-OF-WAY.

9-304(b)

THE PARKING AREA IS NOT BEING MAINTAINED. THERE ARE AREAS OF DAMAGED ASPHALT AND THE STRIPPING IS IN A WORN CONDITION.

9 - 305 (b)

THE GRASS IS OVERGROWN AND MISSING IN AREAS.

FBC 104.9.3.1

PERMIT 02121412 FOR THE WOOD FENCE HAS EXPIRED SINCE NO PASSING INSPECTION HAS BEEN OBTAINED IN OVER 90 DAYS.

CASE NO: CE02121292 CASE ADDR: 640 NE 4 AV

OWNER: SWISS VILLAGE HOLDINGS INC

INSPECTOR: KENNETH REARDON

VIOLATIONS: 47-19.5 D.4.

THE FINISHED SIDE OF THE FENCE IS NOT FACING THE NEIGHBORING PROPERTY ALONG THE REAR AND NORTH SIDE. THE FENCING MUST BE FINISHED ON BOTH SIDES WHERE VISIBLE FROM THE RIGHT-OF-WAY.

9-305(b)

THE GRASS IS OVERGROWN AND MISSING IN AREAS.

9-313(b)

THE BUILDING NUMBERS ARE NOT DISPLAYED AND VISIBLE FROM THE STREET.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL SEPTEMBER 23, 2003

10:00AM

FBC 104.9.3.1

PERMIT 02121414 FOR THE WOOD FENCE HAS EXPIRED SINCE NO PASSING INSPECTION HAS BEEN OBTAINED IN OVER 90 DAYS.

CASE NO: CE02121295 CASE ADDR: 630 NE 4 AV

OWNER: SWISS VILLAGE HOLDINGS INC

INSPECTOR: KENNETH REARDON

VIOLATIONS: 47-19.5 D.4.

THE FINISHED SIDE OF THE FENCE IS NOT FACING THE NEIGHBORING

PROPERTY ALONG THE REAR OF THIS PROPERTY.

9 - 304 (b)

THE PARKING AREA IS NOT BEING MAINTAINED. THERE ARE AREAS OF DAMAGED ASPHALT AND THE STRIPPING IS IN A WORN CONDITION.

9-305(b)

THE GRASS IS OVERGROWN AND MISSING IN AREAS.

FBC 104.9.3.1

PERMIT 02121416 FOR THE WOOD FENCE HAS EXPIRED SINCE NO PASSING INSPECTION HAS BEEN OBTAINED IN OVER 90 DAYS.

CASE NO: CE02121296 CASE ADDR: 634 NE 4 AV

OWNER: SWISS VILLAGE HOLDINGS INC

INSPECTOR: KENNETH REARDON

VIOLATIONS: 47-19.5 D.4.

THE FINISHED SIDE OF THE FENCE IS NOT FACING THE NEIGHBORING

PROPERTY ALONG THE REAR OF THIS PROPERTY.

9 - 304 (b)

THE PARKING AREA IS NOT BEING MAINTAINED. THERE ARE AREAS OF DAMAGED ASPHALT AND THE STRIPPING IS IN A WORN CONDITION.

9 - 305 (b)

THE GRASS IS OVERGROWN AND MISSING IN AREAS.

FBC 104.9.3.1

PERMIT 02121415 FOR THE WOOD FENCE HAS EXPIRED SINCE NO PASSING INSPECTION HAS BEEN OBTAINED IN OVER 90 DAYS.

CASE NO: CE03030960 CASE ADDR: 2711 SW 15 AVE

OWNER: WICKHAM, MARVIN & CAROLYN

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE WINDOWS AND DOORS HAVE BEEN REPLACED AND CARPORT HAS BEEN ENCLOSED WITHOUT FIRST OBTAINING A BUILDING PERMIT. OWNER/BUILDER PERMIT 03070493 FOR WINDOWS AND SHUTTERS ISSUED TO THE PREVIOUS OWNER, HAS BEEN VOIDED BY THE BUILD-

ING OFFICIAL DUE TO A FALSE AFFIDAVIT BEING FILED.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

SEPTEMBER 23, 2003

10:00AM ______

CASE NO: CE03041137 CASE ADDR: 831 SW 28 ST OWNER: DELILLO, MATTHEW J INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.9.3.1

PERMIT 01082449 FOR INSTALLATION OF THE LAWN SPRINKLER SYSTEM AND 01110205 FOR AFTER-THE-FACT INSTALLATION OF TOILET AND SINK, HAVE EXPIRED SINCE NO PASSING INSPECTIONS

HAVE BEEN OBTAINED IN OVER 90 DAYS.

CASE NO: CE03051075 CASE ADDR: 2831 NE 36 ST

OWNER: MCGRAW, THOMAS L & KELI, C

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE AWNING ATTACHED TO THE REAR WALL OF THE HOUSE WAS INSTALLED WITHOUT FIRST OBTAINING A BUILDING PERMIT.

CASE NO: CE03051844 CASE ADDR: 1708 SW 20 ST

HARSTAD, ROBERT M & SEMENICK, PHILLIP A

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE REAR PATIO ROOF STRUCTURE HAS BEEN CONSTRUCTED WITHOUT

FIRST OBTAINING A BUILDING PERMIT.

CASE NO: CE03060008 CASE ADDR: 3673 DAVIE BLVD

OWNER: APERGIS, HARALAMBOS J & MAGDA INSPECTOR: KENNETH REARDON

VIOLATIONS: 15-28

THE CHERILYS BUSINESS CENTER IS OPERATING AT THIS LOCATION

WITHOUT AN OCCUPATIONAL LICENSE.

FBC 104.1

THE INTERIOR WALLS AND AN EXTERIOR WALL SIGN HAVE BEEN INSTALLED WITHOUT FIRST OBTAINING BUILDING PERMITS. THE PERMIT FOR THE WALLS HAS BEEN APPLIED FOR, BUT THE PERMIT

HAS NEVER BEEN ISSUED.

CASE NO: CE03061053 CASE ADDR: 2901 SW 5 ST
OWNER: JONES, CAROLYN INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.9.3.1

PERMITS 97011621, 99030832, 99061912 & 99070759 FOR CONSTRUCTION OF THE TWO STORY TWO BEDROOM ADDITION HAVE EXPIRED SINCE NO PASSING INSPECTIONS HAVE BEEN OBTAINED IN

OVER 90 DAYS.

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL

SEPTEMBER 23, 2003

10:00AM

CASE NO: CE03071396 CASE ADDR: 282 SW 33 CT

OWNER: MARY ANN CASSEL LTD PRTNR

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.2.11

A CENTRAL AIR CONDITIONING SYSTEM HAS BEEN INSTALLED ON THE REAR WALL OF THE BUILDING WITHOUT FIRST OBTAINING A BUILDING

PERMIT.

CASE NO: CE03072072 CASE ADDR: 3101 SW 13 ST

OWNER: SCULLY, JOSEPH L & LINDA

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.9.3.1

PERMIT 03011445 FOR REROOFING, HAS EXPIRED SINCE NO PASSING

INSPECTION HAS BEEN OBTAINED IN OVER 90 DAYS.